

FIG. 1A




FIG. 1B




FIG. 1C




FIG. 2A




FIG. 2B




FIG. 3




FIG. 4A




FIG. 4B




FIG. 5




FIG. 6A




FIG. 6B




FIG. 6C




FIG. 7A




FIG. 7B




FIG. 8







FIG. 9A**FIG. 9B****FIG. 9C**




FIG. 10





FIG. 11B 1g CUTTING PART SLIT-FORMED FERRULE






FIG. 12






FIG. 13A**FIG. 13B**

FIG. 14A**FIG. 14B****FIG. 14C**




FIG. 16A




FIG. 16B





FIG. 17 RELATED ART

23/24






FIG. 18 RELATED ART